


VIN JALESW163D7900979

SUMMIT BODYWORKS USED TRUCK EVALUATION

Year	Make	Model	Box Length	VIN	Builder	Mileage
2013	ISUZU	NQR	18		Summit	30,000

Exterior				
	Working	Damaged	# items in Truck	Description
Cab/Dash/Seats/Fir	✓			
Box	✓			
Decals		✓		MINOR SCRATHES
Glass/Wipers	✓			
Lights/Lens	✓			
Mirrors	✓			
Grill	✓			
Locks				N/A
Wheels/Caps	✓			
Tires	✓			NEW
Interior				
Stereo	✓			
Heater/AC	✓			
Lacing		✓		3 KNOTS TIED
Box/Carpet/Shelves	✓			
Liftgate	✓			
Lights	✓			
AC Big/Small	✓			
Heat Dsl/LP/HW	✓			LP HEAT
Drawers	✓			
Wood	✓			
Inverter	✓			
Converter	✓			
Batteries 4/6	✓			
# Magnets	✓		4	2 SOCKET SHELVES
Alarm	✓			
Major Service done:			Comments	
NORMAL SERVICE			BACK UP camera INTERNAL CAMERA	

I certify the above information is true and correct to the best of my knowledge

Signature 

Date 2-24-17

Print Name ROGER UNGOLO

Please return by fax to 303-288-2847 or by e-mail to sales@summitbodyworks.com